


**L56**  
**Oak**  
Rabbeted Sill  
*1<sup>1</sup>/<sub>16</sub>" x 5<sup>1</sup>/<sub>4</sub>"*

**L57**  
**Oak**  
Rabbeted Sill  
*1<sup>1</sup>/<sub>16</sub>" x 7<sup>1</sup>/<sub>4</sub>"*


**L123**  
**Oak**  
Bar Rail  
*4<sup>13</sup>/<sub>16</sub>"*

**I1J**  
**Paint Grade**  
Interior Jamb Stock  
*1<sup>1</sup>/<sub>16</sub>" x 4<sup>9</sup>/<sub>16</sub>"*


**I2J**  
**Paint Grade**  
Interior Jamb Stock  
*1<sup>1</sup>/<sub>16</sub>" x 5<sup>1</sup>/<sub>4</sub>"*



**L56**



**L57**



**L123**



**I1J**



**I2J**